United States of America

Department of Transportation — Hederal Aviation Administration

Supplemental Type Certificate

Number SA2925NM

This certificate, issued to

AAR Oklahoma, Inc.

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part

Federal Aviation

Regulations.

Original Product - Type Certificater Number: A34CE

Make: Cessna

Medel:

T303, Normal Category

Description of Type Design Change: Installation of a camera hole and viewing port in accordance with AAR Western Drawing List No. T303-CH, dated April 24, 1985.

NOTE: This STC approves the installation of a camera hole and doors, viewing port, the rerouting of elevator, rudder, flap and trim cables around the camera hole with associated electrical and vacuum system provisions. Additional FAA approval will be required for the physical installation of any cameras. See Flight Structure Report No. 84FS139D1, Revision "A", dated March 13, 1985, for camera installation structural considerations.

Limitations and Conditions: Data pertaining to this modification are considered inadequate for duplication in other aircraft. This approval is limited to the installation in Cessna model T303 aircraft, Serial Number T30300206 only. The modified airplane must be operated in accordance with a copy of the FAA Approved Airplane Flight Manual Supplement dated May 15, 1985, or later FAA approved revision. A copy of this Certificate and Airplane Flight Manual Supplement shall be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until sur-

rendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the

Federal Aviation Administration

Date of application: February 8, 1985

Date reissued: July 22, 1988

Date of issuance: May 15, 1985

Date amended:

Bry direction of the Administrator

Manager, Seattle Aircraft Modification Branch

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.